

3

REBEL REPLACEMENT AXLE

BBB ROAD PEDALS
/BPD-51

BBB CYCLING.COM
ROOSEVELTSTRAAT 46, 2321 BM
LEIDEN, THE NETHERLANDS

 EN MANUAL / DE HANDBUCH / FR MANUEL / NL HANDLEIDING / ES MANUAL / PT MANUAL /
IT MANUALE / HU HASZNÁLATI UTASÍTÁS / PL PODRĘCZNIK / CZ UŽIVATELSKÁ PŘÍRUČKA
/ JP 使用説明書 / RU РУКОВОДСТВО ПОЛЬЗОВАТЕЛЯ / SK MANUÁL / NO HÅNDBOK
**WARNING**

Do not tighten the cartridge over suggested torque.

The hex head could be damaged by over tightening.

The tightening direction for cartridge axles are different for drive and non-drive side pedals. The drive side pedal is tightened in counter-clockwise and non-drive side is tightened in clockwise direction.

BBB has no responsibility for misprints or changed technical content.

