


# Receiver and Dome Flow Chart



\*SureFit 2B receivers are no longer available for new orders. The transition to SureFit 2C receivers provides the retention benefits of a single rib nozzle design and additional dome options.

# Receiver, Dome and Sport Lock Compatibility Guide

## Current Receiver, Dome and Sport Lock Portfolio

	Receivers							Domes				Sport Locks	
	M&RIE	SureFit 3			SureFit 2C			SureFit 3				SureFit 3	SureFit 2B
		LP	MP	HP	LP	MP	HP	Open	Tulip	Power	Closed		
ReSound ONE	●	●	●	●	-	-	-	●	●	●	●	●	-
ReSound LiNX Quattro	-	-	-	-	●	●	●	●	●	●	●	-	●
ReSound LiNX 3D	-	-	-	-	●	●	●	●	●	●	●	-	●
ReSound LiNX <sup>2</sup>	-	-	-	-	●	●	●	●	●	●	●	-	●

## Legacy Receiver, Dome and Sport Lock Portfolio

	Receivers			Domes			Sport Locks
	SureFit 2B			SureFit 2			SureFit 2B
	LP	MP	HP	Open	Tulip	Power	
ReSound LiNX Quattro	●	●	●	●	●	●	●
ReSound LiNX 3D	●	●	●	●	●	●	●
ReSound LiNX <sup>2</sup>	●	●	●	●	●	●	●

### Manufacturer according to FDA:

#### GN ReSound North America

8001 E Bloomington Freeway  
 Bloomington, MN 55420  
 USA  
 1-800-248-4327  
 pro.resound.com

### Manufacturer according to Health Canada:

#### ReSound Canada

2 East Beaver Creek Road, Building 3  
 Richmond Hill, ON L4B 2N3  
 Canada  
 1-888-737-6863  
 pro.resound.com